


Asbestos Inspection Report

Ford Parking Garage
1980 Ford Drive
Cleveland, Cuyahoga County, Ohio

July 5, 2022

Terracon Project No. N6227136



Prepared for:

University Circle Inc.
Cleveland, Ohio

Prepared by:

Terracon Consultants, Inc.
Cleveland, Ohio

terracon.com

Terracon

Environmental



Facilities



Geotechnical



Materials



July 5, 2022

University Circle Inc.
10831 Magnolia Drive
Cleveland, Ohio 44106

Attn: Ms. Julie Criscione
JMC Owners Rep Services
E: jcriscione@JMCcorep.com

Re: Asbestos Inspection Report
Ford Parking Garage
1980 Ford Drive
Cleveland, Cuyahoga County, Ohio 44106
Terracon Project No. N6227136

Dear Ms. Criscione:

Terracon Consultants, Inc. (Terracon) is pleased to submit the attached report for the above-referenced site to University Circle Inc. (Client). The purpose of this report is to present the results of an asbestos inspection and observations for other hazardous materials items which was performed at the site on June 13, 2022. The asbestos inspection was conducted in general accordance with Terracon Proposal No. PN6227136 dated May 2, 2022. We understand the asbestos inspection was requested due to the planned demolition of the existing on-site parking garage structure.

Asbestos-containing materials were not identified as a result of this inspection. Please see the attached report for further detail.

Terracon appreciates the opportunity to provide this service to University Circle Inc. If you have any questions regarding this report, please contact the undersigned at (216) 459-8378.

Sincerely,
Terracon Consultants, Inc.

Wade R. Mangus
Project Manager
OH AHES #35877

Kate E. Baney
Department Manager – Asbestos,
Lead Paint, and IH Services
OH AHES #34423



Terracon Consultants, Inc. 12460 Plaza Drive Cleveland, Ohio 44130
P (216) 459-8378 F (216) 459-8954 terracon.com

Environmental

Facilities

Geotechnical

Materials